From: Laija, Emerald

 To:
 MOORE.Fredrick@deq.state.or.us

 Subject:
 RE: Soil Sampling at the Scrubber Ponds

 Date:
 Tuesday, March 12, 2013 10:57:00 AM

Attachments: image001.png

No worries. It's your first time seeing the document. I've had a lot more time working on it.

-Emy

Emerald Laija, Environmental Scientist U.S. Environmental Protection Agency Hanford Project Office 309 Bradley Blvd, Suite 115 Richland, WA 99352

Phone: 509 376-4919

E-mail: laija.emerald@epa.gov

From: MOORE Fredrick [mailto:MOORE.Fredrick@deq.state.or.us]

Sent: Tuesday, March 12, 2013 9:14 AM

To: Laija, Emerald

Subject: RE: Soil Sampling at the Scrubber Ponds

Hi Emy, yes, my bad. For some reason my brain just focused on the fencing and didn't see the additional soil sampling. I'll try and be a better reviewer. Cheers, Fredrick

From: Laija, Emerald [mailto:Laija.Emerald@epa.gov]

Sent: Tuesday, March 12, 2013 9:09 AM

To: MOORE Fredrick

Subject: RE: Soil Sampling at the Scrubber Ponds

Fredrick,

Table 6 on page 42 of the draft five-year review lists soil sampling of the soil cover under item 4 in the recommendation column. Is this the table to which you are referring?

ı	unucisioou							ı
	4. Ecological receptors are entering the Scrubber Sludge Ponds area	Modify fencing to prevent entrance of ecological receptors to the Site. Conduct soil sampling to determine integrity of soil cover.	Lockheed	EPA	December 2013	Yes	Yes	
	Uncertainty							ı

Emerald Laija, Environmental Scientist U.S. Environmental Protection Agency Hanford Project Office 309 Bradley Blvd, Suite 115 Richland, WA 99352

Phone: 509 376-4919 E-mail: <u>laija.emerald@epa.gov</u>

From: MOORE Fredrick [mailto:MOORE.Fredrick@deq.state.or.us]

Sent: Friday, March 08, 2013 3:32 PM

To: Laija, Emerald

Subject: Soil Sampling at the Scrubber Ponds

Hi Emy, I see in the recommendations in the front in the draft 5-year review includes soil sampling at the scrubber

ponds but the table in the back of the report doesn't list it. I assume the table should list soil sampling at the scrubber ponds?

Cheers, Fredrick

Fredrick Moore DEQ Eastern Region 475 NE Bellevue Dr. Bend, OR 97701

541.633.2011 moore.fredrick@deq.state.or.us